



_														_
REC COP			COPY NO.	PUB. DATE		LOCATION			MAST	ER	DATE RECEIVED	LOCATION		
			D I ACOSTO	æd Þðf Reid	ease	2004/0	5/05 :	¢Ιλ	RDF	78T0	5161A000600010081-4	MAXIMUM	3	
CUT COP	TO IES	0	7/72	CUT TO COPIES		DATE		COPI	ES DE	STROY	ED			
CUT TO COPIES			DATE	CUT TO COPIES		DATE								
CUT TO COPIES			DATE	MASTER		DATE								
DATE					NUMBER OF COPIES			DATE				NUMBER OF COPIES		
мо.	MO. DAY YR.		RECEIVED OR	ISSUED	REC	'D ISS'D	BAL	MO.	DAY	YR.	RECEIVED OR ISSUED	REC D	188'0	BAL
9	5	68	Dict. Unit #	41 - 43	3		3							
[]	18	70	NPIO #	41			ಎ							
8	3	12	NAIU #	- 43			0	W	K	6				
														-
								ļ						
														-
								ļ						
			Anara	and East Dale		2004/	EINE :	CIA	DDC	70T	)5161A000600010081-4	4		
TITI	- E		Approv	<del>reu For Rel</del>	<del>easc</del>	<del>:  <u> </u></del>	<del>: 0/U3</del>	SET	LV:	<del>7/0  </del>	100 AT 10 N	+		25X
X1	NI	P1C [	I	PIR 65136	Ma	ay 1966	5 '	TS			2.5	5138		20/



PREPARED BY:
CHEMICAL AND SCIENTIFIC SECTION
INDUSTRIAL BRANCH, IAD



25X

CIA IMAGERY ANALYSIS DIVISION

## LU-CHOU NITROGEN FERTILIZER PLANT LU-CHOU, CHINA

The Lu-chou Nitrogen Fertilizer Plant is located at 28 46N - 105 22E and is approximately 8 nm south-southwest of Lu-chou (Lu-hsien) in Szechwan Province, China (Figures 1 and 2). The plant is situated near the village of Na-ch'i on the east bank of the Ch'ang Chiang (Yangtze River) and is served by water as well as by road.

The plant is in a mid-stage of construction on the latest coverage Figure 5). Analysis of this coverage indicates that it will produce synthetic ammonia and prilled urea. Natural gas probably will be used to produce the hydrogen necessary for ammonia synthesis. The specific facilities present at this stage of construction have been identified on Figure 5. All available photographic coverage during the period was examined in order to follow the construction of this plant. Enlargements from the best coverage have been included. The following discussion describes the significant changes and activity by mission (all annotation numbers refer to Figure 5): Figure 3 - The smaller of the two power plants (Annotation 5), an associated control building and spray pond (Annotation 6) were present at this time. One of the fabrication buildings (Annotation 12) was under construction and excavation for the small gasholder (Annotation 8) had begun. Operation of the spray pond indicated that the small power plant was in use. - The small gasholder and fabrication building mentioned under (1) appeared nearly complete while construction of three other fabrication buildings was underway. A water treatment facility, a processing building, and a wharf (Annotations 14, 15 and 17) were also under construction. Construction of a bridge over the Yung-ning Ho (Annotation 18) and additional road construction in the plant area were in progress. The spray pond was operating, indicating that the small power plant was in use. Figure 4 - The larger power plant (Annotation 5) was in a mid-stage of construction and the bridge (Annotation 18) appeared nearly complete. Further progress on the wharf (Annotation 17) was noted. The ammonia synthesis building, urea prilling tower, and settling tanks (Annotations 4, 9, and 11) were


under construction.

CIA IMAGERY ANALYSIS DIVISION

(4) Figure 5 - The prilling tower, the four fabrication buildings, and the water treatment facility (Annotations 9, 12, and 14) appeared complete on this mission. The larger power plant (Annotation 5) also appeared complete and in operation as indicated by smoke coming from its stacks. In addition, the spray pond was in operation indicating that either one or both power plants were in use. Construction of a cooling tower and water intake (Annotations 1 and 16) had taken place. Under construction were two probable spheroidal tanks, the ammonia synthesis building, a probable prilled urea storage building, and a conveyor (Annotations 3, 4, 10, and 13). The footings for a conveyor or pipeline were under construction (Annotation 7) as well as pipelines serving the various facilities. A tall structure was apparent

on the southwest side of the processing building (Annotation 15).





LU-CHOU NITROGEN FERTILIZER PLANT LU-CHOU, CHINA 28 46N - 105 22E

25)



25X1